

## **UPDATE REGARDING SERVICE ALERT/ETHANOL-BLEND FIX**

Dear customers,
We notified users about our <i>PX375-TC#7</i> , <i>PX375-TC-28v#7</i> , and <i>PX375-S</i> models and their susceptibility to ethanol-blended fuels back in October 2022. In November we released an update regarding pump unit revision changes (#8 & C#4 models) and announced that we had begun the process of retrofitting new components or modifying existing components that incorporate the necessary changes needed for ethanol blends.
Since then, we have received many units back for our free upgrade/retrofit.
We now wish to notify all customers that may still be affected by this issue: the cut-off date for the F.O.C ethanol-blend fix is October 1 <sup>st</sup> , 2023. Thereafter, there will be a fee of 220.00 GBP.
We encourage all customers still using an ethanol-blend fuel with Andair pumps (#7, S#1 or earlier) to discontinue immediately and contact Andair for guidance, or to return their units for inspection, repair/replacement.
Thank you for your continued custom and support!
Andair Team.