

## SERVICE ALERT

Issued October 6<sup>th</sup>, 2022

This service alert applies to all Andair fuel pump models E.g., **PX375-TC, PX500-TC, PX375D-PR, PX375-S**, etc.

It has come to our attention that the use of ethanol-based fuel (E10, E15, etc) over time can cause detriment and weakness to the epoxy adhesive/potting compound used in our pump models. Eventually this will inhibit conforming/working functionality of pump components.

We encourage all customers using ethanol-based fuels with Andair pump models to discontinue immediately and contact Andair for guidance, or to return their units for inspection, repair/replacement.

***We are currently working on a solution to resolve this matter, so all fuel types are sufficient without risk or harm to your Andair pump model. In the meantime, we strongly urge you to suspend the use of ethanol-based fuel until further notice.***

The use of UL91, Avgas 100LL, UL94 & Swift 100R is safe and satisfactory in all Andair products.

We apologise for any concern or inconvenience this may cause. Thank you for your continued custom and support!

Andair Team.